

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	191327 KM
<b>File nr. :</b>	1422790	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FFT063 / VF1JZ14M649329420 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	17/06/2013
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	RENAULT / GRAND SCENIC	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	12290	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ALKEN MAES NV	<b>Co2:</b>	105g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	5 [x]
<b>Vehicle type :</b>	GRAND SCENIC Expression 5pl.110PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	X3
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT	X2			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	BONNET/CENTER/LEFT	DENT	HAGEL			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
2	I 1	i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

[x] ROOF/CENTER/LEFT		DENT		HAGEL	
Number	Code	Description	Unit price	Depr.	Total
2	I 2 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		195.60 EUR

### Others

#### CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

#### RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	293.40	82.80	308.20	211.80	95.00	0	0	0	0
14.58	293.40	82.80	154.10	105.90	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
485.78	520.00	0	<b>1005.78</b>
HOG: 0	BG: 0		NA Deprec. 745.78
			0.00%
			<b>TOTAL 745.78</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/07/2017 <b>Hour :</b> 09:19 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	