

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	94763 KM
File nr. :	1415753	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HUH472 / SB1MS3JE50E105549 /		yr of constructionr :	/
E-File nr. :		First registration :	06/10/2014
VFS-nr. :		Color :	WHITE
Make + Model :	TOYOTA / AURIS TOURING SPORTS	Fuel type :	HYBRID
Object nr. :	843125BE300002	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TOYOTA MOTOR EUROPE	Co2:	91g/km
Driver :		Remote controls:	1
Covering :	TISSUE-LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	INT. = STOF / SIMILI TREKHAAK IN DE KOFFER		

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2: NOK [x]	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] DUNLOP	Tyre : OK [x] 0-1.6/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RL : [x] DUNLOP	Tyre : OK [x] 4-6/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel FR : [x] DUNLOP	Tyre : [x] OK [x] 0-1.6/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RR : [x] DUNLOP	Tyre : OK [x] 4-6/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RES: [x] ANDERE	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	W
Rear tyre	225	45	R	17	W

Remark : REP. KIT OK

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT MUDGUARD/LEFT/FRONT	CHIPS

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE	MEERDERE KRASSEN	
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
7	0 LU =0.00 EUR	254.16 EUR	50 %	254.16 EUR

[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
6	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR

[x]	FRONT DOOR/LEFT/FRONT	DENT		
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
5	0 LU =0.00 EUR	382.02 EUR	50 %	382.02 EUR

[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
8	0 LU =0.00 EUR	382.02 EUR	50 %	382.02 EUR

[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
4	0 LU =0.00 EUR	254.16 EUR	50 %	254.16 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	MISSING/INCOMPLETE		
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
3	0 LU =0.00 EUR	0 EUR	50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	11.47 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	MIRROR COVER	144.00 EUR	50 %	144.00 EUR

1	2	3	4	5	6	7	8	9	10
11.47	285.00	144.00	254.16	382.02	115.56	254.16	382.02	0	0
11.47	285.00	72.00	127.08	191.01	115.56	127.08	191.01	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
412.03	1416.36	0	1828.39
HOG: 0	BG: 2		NA Deprec. 1120.21
			0.00%
			TOTAL 1120.21

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/07/2017 Hour : 10:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	