

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	102106 KM
File nr. :	1412526	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DLF069 / JTDKN36U305447835 /		yr of constructionr :	/
E-File nr. :		First registration :	14/06/2012
VFS-nr. :		Color :	RED
Make + Model :	TOYOTA / PRIUS	Fuel type :	HYBRID
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	92g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PRIUS Hybrid Lounge 98PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	
Number of gears:		Number of doors:	5
HP:	99	kW:	73
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : NOK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate : NOK [x]
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] TOYO Tyre : OK / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : OK / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] TOYO Tyre : OK / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	17	V
Rear tyre	215	45	R	17	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	ONDER
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	ONDER

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR	
[x]	FRONT DOOR/RIGHT/CENTER	OTHER DAMAGES	SLECHT HERSTELD - WEMEL			
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Interior

[x]	FLOOR BOOT	CUT / TORN				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR
[x]	BOOT LID IN	SCRATCHED				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
174.96	310.50	211.80	285.00	0	0	0	0	0	0
174.96	155.25	105.90	285.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
459.96	522.30	0	982.26
HOG: 0	BG: 0		NA Deprec. 721.11
			0.00%
			TOTAL 721.11

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/06/2017 Hour : 09:25 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	