

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	145088 KM
File nr. :	1421083	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EYT838 / VF1JZ140648764522 /		yr of constructionr :	/
E-File nr. :		First registration :	24/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	46483	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD PROFESSIONALS NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SCENIC Energ.Expression 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/CORNER

DENT

Repair paint - LI

New paint - E

Depr.

Total

4 0 LU =0.00 EUR 211.80 EUR 50 % 211.80 EUR

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR

[x] REAR MUDGUARD/RIGHT/FRONT

DENT

Repair paint - LI

New paint - E

Depr.

Total

5 0 LU =0.00 EUR 308.20 EUR 50 % 308.20 EUR

[x] REAR DOOR/LEFT/FRONT

SCRATCH WITH PAINT DAMAGE

Repair paint - LI

New paint - E

Depr.

Total

3 0 LU =0.00 EUR 318.35 EUR 50 % 318.35 EUR

[x] REAR DOOR/RIGHT/FRONT

DENT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

[x] FRONT DOOR/LEFT/REAR

SCRATCH WITH PAINT DAMAGE

+DEUK

Repair paint - LI

New paint - E

Depr.

Total

2 0 LU =0.00 EUR 318.35 EUR 50 % 318.35 EUR

[x] WINDSCREEN/CENTER/LEFT

HOLE/CRACK/TORN

Repair paint - LI

New paint - E

Depr.

Total

1 0 LU =0.00 EUR 0 EUR 50 %

Repair paint - LI

New paint - E

Depr.

Total

1 25 LU =120.00 EUR 0 EUR 50 % 120.00 EUR

[x] FRONT DOOR/RIGHT/REAR

SCRATCH WITH PAINT DAMAGE

+DEUK

Repair paint - LI

New paint - E

Depr.

Total

7 0 LU =0.00 EUR 318.35 EUR 50 % 318.35 EUR

[x] BONNET/CENTER/LEFT		OTHER DAMAGES	HAGELSCHADE		
Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] ROOF/CENTER/LEFT		OTHER DAMAGES	HAGELSCHADE		
Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
8	15	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		72.90 EUR

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
1	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
547.20	318.35	318.35	327.36	308.20	63.00	318.35	72.90	0	0
273.60	159.18	159.18	221.46	154.10	63.00	159.18	72.90	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
251.46	2022.25	0	2273.71
HOG: 0	BG: 0		NA Deprec. 1262.58
			0.00%
			TOTAL 1262.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/07/2017 Hour : 12:54 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	