

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	147744 KM
File nr. :	1422203	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJK055 / WWZZZ3CZEE018306 /		yr of constructionr :	/
E-File nr. :		First registration :	16/07/2013
VFS-nr. :		Color :	BLUE D
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	35672	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	FORCEA NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	PASSAT VAR Comfortline BMT 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate : OK
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	MICHELIN	Tyre :	OK	/		Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/		Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/LEFT/Front	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	REAR MUDGUARD/RIGHT/Front	DENT		
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	REAR DOOR/RIGHT/Front	DENT	+ KRAS	
[x]	BONNET/CENTER/LEFT/Front	CHIPS		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
1	0	LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	BONNET/CENTER/LEFT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	290.08	211.80	63.00	0	0	0	0	0	0
105.90	145.04	105.90	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	713.68	0	776.68
HOG: 0	BG: 0		NA Deprec. 419.84
			0.00%
			TOTAL 419.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/07/2017 Hour : 10:11 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	