

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	126430 KM
File nr. :	1417729	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FDU730 / WVVZZZAUZDW146682 /		yr of constructionr :	/
E-File nr. :		First registration :	03/06/2013
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	6442	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	UNISYS BELGIUM NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR THRESHOLD/RIGHT/REAR	DENT	BINNENIN		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR
[x]	WINDSCREEN/LEFT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
58.32	487.20	310.50	0	0	0	0	0	0	0
58.32	243.60	155.25	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	797.70	0	856.02
HOG: 0	BG: 0		NA Deprec. 457.17
			0.00%
			TOTAL 457.17

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 11:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	