

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	188657 KM
File nr. :	1421345	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FAD341 / VF1JZ140648764521 /		yr of constructionr :	/
E-File nr. :		First registration :	03/05/2013
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	49284	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD PROFESSIONALS NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SCENIC Energ.Expression 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	0 EUR		50 %	

[x] FRONT DOOR/LEFT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	0 EUR		50 %	

[x] BONNET/CENTER/LEFT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	14.40 EUR	50 %	14.40 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	14.40 EUR	50 %	14.40 EUR

1	2	3	4	5	6	7	8	9	10
290.08	63.00	308.20	28.80	0	0	0	0	0	0
145.04	63.00	154.10	14.40	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	627.08	0	690.08
HOG: 0	BG: 0		NA Deprec. 376.54
			0.00%
			TOTAL 376.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/07/2017 Hour : 14:57 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	