

C3U6LR

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	175198 KM
File nr. :	1423842	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
SE4092 / WVWZZZ3CZEE132021 /		yr of constructionr :	/
E-File nr. :		First registration :	28/07/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : NOK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate : [x]
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] GOODYEAR Tyre : OK [x] >6/ Rim : / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] GOODYEAR Tyre : OK [x] >6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
487.20	0	0	0	0	0	0	0	0	0
243.60	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	487.20	0	487.20
HOG: 0	BG: 0		NA Deprec. 243.60
			0.00%
			TOTAL 243.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/07/2017 Hour : 08:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	