

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                                 |                                 |                               |
|-------------------------------------|---------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING                 | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                                 | <b>Mileage :</b>                | 133184 KM                     |
| <b>File nr. :</b>                   | 1421016                         | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                                 | <b>Mileag ref. service :</b>    | 0                             |
| 1KFK517 / TMBJJ73T3C9046647 /       |                                 | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                                 | <b>First registration :</b>     | 22/04/2015                    |
| <b>VFS-nr. :</b>                    |                                 | <b>Color :</b>                  | BLACK                         |
| <b>Make + Model :</b>               | SKODA / SUPERB COMBI            | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 36475                           | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                                 | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | REGIONALE MEDIA<br>MAATSCHAPPIJ | <b>Co2:</b>                     | 114g/km                       |
| <b>Driver :</b>                     |                                 | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE                          | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                         | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               |                                 | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   |         | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BREAK   | <b>Engine size:</b>        | 1598    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 5       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 105     | <b>kW:</b>                 | 77      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> | No      |
|                                     |         | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |         |                            |         |

|                              |    |                         |                       |     |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number :   | OK | Service manual :        | OK                    | [x] |
| Cert. of reg. / Part 1:      | OK | [x]                     | Cert. of conformity : | OK  |
| Cert. of reg. copy / Part 2: |    | Insurance certificate : |                       |     |
| Warning vest :               | OK | [x]                     | Transport licence :   |     |
| Tax certificate :            |    | Navigation CD/SD/DVD    |                       |     |
| Fuel card :                  |    | Car radio :             | OK                    | [x] |
| Mobile phone kit :           |    | Extinguisher :          | OK                    | [x] |
| First aid kit :              | OK | [x]                     | Warning triangle :    | OK  |
| Jack, wheelspanner :         |    | Oil level :             | OK                    | [x] |
|                              |    | Filled up :             | 0                     |     |

## Wheels and tyres: Summer tires

|            |     |             |        |     |     |      |       |       |                 |                 |          |          |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL:  | [x] | MICHELIN    | Tyre : | OK  | [x] | 2-4/ | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK  | [x] | 2-4/ | Rim : |       |                 | /               | Hubcap : |          |
| Wheel FR : | [x] | MICHELIN    | Tyre : | [x] | OK  | [x]  | 2-4/  | Rim : | [x]             | WHEEL SCRATCHED | /        | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK  | [x] | 2-4/ | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RES: | [x] |             | Tyre : | OK  |     | /    | Rim : |       |                 | /               | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 16  | V     |
| Rear tyre  | 205   | 55     | R    | 16  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                          |                           |              |              |
|-----|--------------------------|--------------------------|---------------------------|--------------|--------------|
| [x] | REAR BUMPER/CENTER/LEFT  |                          | SCRATCH WITH PAINT DAMAGE |              |              |
|     |                          | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b> |
| 4   | 0 LU =0.00 EUR           | 211.80 EUR               |                           | 50 %         | 211.80 EUR   |
| [x] | REAR MUDGUARD/LEFT/Front |                          | SCRATCH WITH PAINT DAMAGE | +DEUK        |              |
|     |                          | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b> |
| 3   | 0 LU =0.00 EUR           | 308.20 EUR               |                           | 50 %         | 308.20 EUR   |
| [x] | REAR DOOR/RIGHT/Front    |                          | SCRATCH WITH PAINT DAMAGE | +DEUK        |              |
|     |                          | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b> |
| 5   | 0 LU =0.00 EUR           | 318.35 EUR               |                           | 50 %         | 318.35 EUR   |
| [x] | BONNET/CENTER/LEFT/Front |                          | OTHER DAMAGES             |              |              |
|     |                          | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR           | 0 EUR                    |                           | 50 %         |              |
|     |                          | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b> |
| 2   | 5 LU =24.00 EUR          | 0 EUR                    |                           | 50 %         | 24.00 EUR    |

### Others

#### RIM FRONT LEFT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

#### RIM FRONT RIGHT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

### Pieces

| Number | Code            | Description | Unit price | Depr. | Total     |
|--------|-----------------|-------------|------------|-------|-----------|
| 2      | 1 SKODA EMBLEEM |             | 30.00 EUR  | 50 %  | 30.00 EUR |

| 1      | 2     | 3      | 4      | 5      | 6 | 7 | 8 | 9 | 10 |
|--------|-------|--------|--------|--------|---|---|---|---|----|
| 190.00 | 54.00 | 308.20 | 211.80 | 318.35 | 0 | 0 | 0 | 0 | 0  |
| 190.00 | 27.00 | 154.10 | 105.90 | 159.18 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 190.00     | 892.35      | 0       | <b>1082.35</b>      |
| HOG: 0     | BG: 0       |         | NA Deprec. 636.18   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 636.18</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 24/07/2017 <b>Hour :</b> 13:29<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>   |                                |