

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	125145 KM
File nr. :	1419443	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EZW978 / WVGZZZ1TZDW099739 /		yr of constructionr :	/
E-File nr. :		First registration :	02/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / TOURAN	Fuel type :	DIESEL
Object nr. :	69682	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Prodware Belgium sa	Co2:	121g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	TOURAN Highline BMT Start/Stop 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1598
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE					
			Repair paint - LI	New paint - E		Depr.	Total	
2	0 LU =0.00 EUR		211.80 EUR			50 %	211.80 EUR	
[x]	REAR DOOR/RIGHT/FRONT		DENT					
	Number	Code	Description		Unit price	Depr.	Total	
3	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR	
[x]	FRONT THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE			+DEUK		
			Repair paint - LI	New paint - E		Depr.	Total	
1	0 LU =0.00 EUR		310.50 EUR			50 %	310.50 EUR	

1	2	3	4	5	6	7	8	9	10
310.50	211.80	63.00	0	0	0	0	0	0	0
155.25	105.90	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	522.30	0	585.30
HOG: 0	BG: 0		NA Deprec. 324.15
			0.00%
			TOTAL 324.15

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/07/2017 Hour : 11:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	