

www.vabfleetservices.be Date: 27/07/2017 1/4

C14U8Z

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION

LECTION [ ] DELIVERY

Yes

[x] = Status Modification

VAT over the margin - car:

No

Commissionar:	KBC REMARKETING	Cleaniness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	155758 KM
File nr. :	1421817	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCJ174 / WVWZZZ3CZI	DP050800 /	yr of constructionr :	/
E-File nr. :		First registration :	23/05/2013
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	26232	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	HARVEY NASH IT CONSULTING NV	Co2:	114g/km
Driver :		Remote controls:	1
Covering:	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT BER Comfortline BMT 105PK	Country registration :	BELGIUM

Variant car:	BERLINE	Engine size:	1598			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	4			
HP:	105	kW:	77			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:				
		Use:	Unknown			
General condition:						

Metallic paint:



Date: 27/07/2017 www.vabfleetservices.be 2/4

Original registr. number : OK Service manual :

Cert. of reg. / Part 1:

Cert. of reg. copy / Part 2: [x] OK

Warning vest:

Tax certificate:

Fuel card :

Mobile phone kit :

OK First aid kit : [x]

Jack, wheelspanner :

Cert. of conformity: OK

Insurance certificate:

Transport licence:

Navigation CD/SD/DVD

Car radio:

Extinguisher: OK

Warning triangle: OK [x]

OK

[x]

[x]

[x]

Oil level: OK

Filled up : 0

#### Wheels and tyres: Winter tires

Wheel FL:	[X]	PIRELLI	Tyre:		OK	[X]	4-6 /	Rim:	/	Hubcap :
Wheel RL:	[x]	PIRELLI	Tyre:		OK	[x]	4-6 /	Rim:	/	Hubcap:
Wheel FR:	[x]	PIRELLI	Tyre:	[x]	OK	[x]	4-6 /	Rim:	/	Hubcap:
Wheel RR:	[x]	PIRELLI	Tyre:		OK	[x]	4-6 /	Rim:	/	Hubcap:
Wheel RES:	[x]		Tvre:		OK		/	Rim:	/	Hubcan:

[x]	Width	Height	Туре	Rim	Index
Front tyre	235	45	R	17	M+S
Rear tyre	235	45	R	17	M+S

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim :	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 27/07/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

#### Bodywork \& windows

[x] WINDSCREEN/CENTER/RIGHT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT DENT

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
211.80		0	211.80	0
105.90	NA Deprec.		BG: 0	HOG: 0
	0.00%			
105 90	TOTAL			



www.vabfleetservices.be Date: 27/07/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min		
NOT EXECUTED Reason:	): No	<b>_</b>		<u> </u>			
Remark :							
Prices in EUR	without VAT						
Authorized by customer :			Executed by VAB Fleet	Services			
Remark authorize	d customer :						
Date :	27/07/2017	<b>Hour:</b> 11:14					
Company:							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorize	d by customer						