

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	37889 KM
File nr. :	1436255	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EJV256 / WAUZZZ8K2DA175869 /		yr of constructionr :	/
E-File nr. :		First registration :	02/01/2013
VFS-nr. :		Color :	BLUE
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	33153	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG TSRS CVBA	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A4 BER TDie 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	DEELS POLIJSTEN
[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR WINDOW/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	ONDER
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	310.50 EUR		50 %	334.50 EUR

Interior

[x]	ROOF UPHOLSTERY	BURNT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-intv1r-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-intv1r-02	SUPPL VELOURS REPAIR	18.00 EUR		18.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	334.50	82.32	0	0	0	0	0	0	0
105.90	167.25	82.32	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
82.32	546.30	0		628.62
HOG: 0	BG: 0		NA Deprec.	355.47
			0.00%	
			TOTAL	355.47

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 10:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	