

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	190777 KM
<b>File nr. :</b>	1428343	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GHZ891 / WAUZZZ4G8EN096931 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	13/02/2014
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	AUDI / A6 AVANT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>	L	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INS/FLEET NV	<b>Co2:</b>	132g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1968
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

<b>Original registr. number :</b> OK	<b>Service manual :</b> NOK [x] MISSING/INCOMPLETE
<b>Cert. of reg. / Part 1:</b> OK [x]	<b>Cert. of conformity :</b> OK
<b>Cert. of reg. copy / Part 2:</b> NOK [x]	<b>Insurance certificate :</b>
<b>Warning vest :</b> OK [x]	<b>Transport licence :</b>
<b>Tax certificate :</b>	<b>Navigation CD/SD/DVD</b> OK [x]
<b>Fuel card :</b>	<b>Car radio :</b> OK [x]
<b>Mobile phone kit :</b>	<b>Extinguisher :</b> OK [x]
<b>First aid kit :</b> OK [x]	<b>Warning triangle :</b> OK [x]
<b>Jack, wheelspanner :</b>	<b>Oil level :</b> OK [x]
	<b>Filled up :</b> 0

## Wheels and tyres: Summer tires

<b>Wheel FL:</b> [x] PIRELLI Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
<b>Wheel RL :</b> [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
<b>Wheel FR :</b> [x] PIRELLI Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
<b>Wheel RR :</b> [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
<b>Wheel RES:</b> [x] ANDERE Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	16	Y
Rear tyre	225	60	R	16	Y

**Remark :** REP. KIT OK

## Wheels and tyres:

<b>Wheel FL:</b> Tyre : OK / Rim : / Hubcap :
<b>Wheel RL :</b> Tyre : OK / Rim : / Hubcap :
<b>Wheel FR :</b> Tyre : OK / Rim : / Hubcap :
<b>Wheel RR :</b> Tyre : OK / Rim : / Hubcap :
<b>Wheel RES:</b> Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

**Remark :**

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	3X
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	

### Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	<b>0</b>
HOG: 0	BG: 2		NA Deprec. <b>0</b>
			0.00%
			<b>TOTAL 0</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 06/09/2017 <b>Hour :</b> 09:00 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	