

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                 |                                 |                               |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                 | <b>Mileage :</b>                | 178810 KM                     |
| <b>File nr. :</b>                   | 1437601         | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                 | <b>Mileag ref. service :</b>    | 0                             |
| 1HNR075 / WF0GXXGBBGEJ53187 /       |                 | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                 | <b>First registration :</b>     | 29/08/2014                    |
| <b>VFS-nr. :</b>                    |                 | <b>Color :</b>                  | BLACK                         |
| <b>Make + Model :</b>               | FORD / MONDEO   | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 10401           | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             | C               | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | Devoteam NV     | <b>Co2:</b>                     | 109g/km                       |
| <b>Driver :</b>                     |                 | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE          | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE         | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               |                 | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   |         | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BREAK   | <b>Engine size:</b>        | 1560    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 6       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 116     | <b>kW:</b>                 | 85      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> |         |
|                                     |         | <b>Use:</b>                | Unknown |

**General condition:**

|                              |    |                         |                       |     |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number :   | OK | Service manual :        | OK                    | [x] |
| Cert. of reg. / Part 1:      | OK | [x]                     | Cert. of conformity : | OK  |
| Cert. of reg. copy / Part 2: |    | Insurance certificate : |                       |     |
| Warning vest :               |    | Transport licence :     |                       |     |
| Tax certificate :            |    | Navigation CD/SD/DVD    |                       |     |
| Fuel card :                  |    | Car radio :             | OK                    | [x] |
| Mobile phone kit :           |    | Extinguisher :          | OK                    | [x] |
| First aid kit :              | OK | [x]                     | Warning triangle :    | OK  |
| Jack, wheelspanner :         |    | Oil level :             | OK                    | [x] |
|                              |    | Filled up :             | 0                     |     |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |      |       |       |          |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|
| Wheel FL:  | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | /     | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | /     | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK  | [x]  | 2-4/  | Rim : | /        |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | /     | Hubcap : |
| Wheel RES: | [x] |          | Tyre : | OK  | /   |      | Rim : | /     | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215   | 60     | R    | 16  | H     |
| Rear tyre  | 215   | 60     | R    | 16  | H     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR MUDGUARD/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)
- [x] BONNET/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

### Interior

- [x] SEAT FL STAIN

## STATUS: NOT ACCEPTABLE

### Interior

- [x] FLOOR FL CUT / TORN

| Number | Code | Description     | Unit price                                 | Depr.     | Total     |
|--------|------|-----------------|--|-----------|-----------|
| 1      | I 1  | i-vab-inttap-01 | CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER) | 43.92 EUR | 43.92 EUR |

| 1     | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|---|---|---|---|---|---|---|---|----|
| 43.92 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 43.92 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                    |
|------------|-------------|---------|--------------------|
| 43.92      | 0           | 0       | <b>43.92</b>       |
| HOG: 0     | BG: 0       |         | NA Deprec. 43.92   |
|            |             |         | 0.00%              |
|            |             |         | <b>TOTAL 43.92</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 12/09/2017 <b>Hour :</b> 14:12<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |