

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	189025
File nr. :	1435517	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCA015 / WF0LXXGCBLDP28150 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	21/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RL :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	MICHELIN	Tyre :	[x]	NOK	[x]	2-4/	Rim :	/	Hubcap :	SCRATCHED
Wheel RR :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	SCRATCHED	
Wheel RES:	[x]	Tyre :	OK	[x]	/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	WINTER H
Rear tyre	205	55	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/LEFT	CHIPS
[x]	FRONT BUMPER/RIGHT	CHIPS
	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	STEERING WHEEL	SCRATCHED
[x]	FLOOR FL	HOLE
	BOOT LID IN	SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 14:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	