

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	77533 KM
File nr. :	1433375	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEM538 / WF0LXXGCBLDP36756 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	SILVER
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. EConetic Titanium 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	KUNSTSTOF
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/RIGHT	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR LIGHT/LEFT/CORNER	HOLE/CRACK/TORN				
		Repair paint - LI	New paint - E	Depr.	Total	
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	FRONT MUDGUARD/LEFT/REAR	DENT		LAKSCHADE		
	Number	Code	Description	Unit price	Depr.	Total
1	11	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Accessories and others

[x]	ANTENNA	MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

	Number	Code	Description	Unit price	Depr.	Total
2	1	ANTENNE		15.00 EUR	50 %	15.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT		90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	15.00	114.00	0	0	0	0	0	0	0
63.00	7.50	57.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	129.00	0	192.00
HOG: 0	BG: 0		NA Deprec. 127.50
			0.00%
			TOTAL 127.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK / DAKDRAGERS IN KOFFER		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/09/2017 Hour : 15:53 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	