

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	84238 KM
<b>File nr. :</b>	1437624	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1NNE625 / JMBXDGG2WGZ013040 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/03/2016
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	MITSUBISHI / OUTLANDER	<b>Fuel type :</b>	HYBRID
<b>Object nr. :</b>	940	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 6
<b>Customer company :</b>	THERABEL PHARMA SA	<b>Co2:</b>	42g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1998
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	121	<b>kW:</b>	89
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	18	V
Rear tyre	225	55	R	18	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/CENTER/LEFT DENT

[x] FRONT DOOR/LEFT/CENTER DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR LIGHT/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
5 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] REAR MUDGUARD/LEFT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR MUDGUARD/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR DOOR/LEFT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] ROOF STYLE/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
10 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] REAR DOOR/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] WINDSCREEN/LEFT WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
9 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x]	FRONT DOOR/RIGHT/REAR		DENT			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
8	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR		220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	20 LU =96.00 EUR		0 EUR	235.80 EUR	50 %	331.80 EUR

## Interior

[x]	CENTER CONSOLE		MISSING/INCOMPLETE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR
[x]	ROOF UPHOLSTERY		MISSING/INCOMPLETE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR

## Others

### CLEANLINESS INTERIOR

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		43.74 EUR

### RIM FRONT LEFT

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

### RIM REAR LEFT

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

### RIM REAR RIGHT

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR		50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
5	1	REFLECTOR	25.00 EUR	50 %	25.00 EUR
9	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
1	1	OPBERGVAK	150.00 EUR	50 %	150.00 EUR
10	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR

1	2	3	4	5	6	7	8	9	10
241.74	735.00	220.18	626.55	260.80	308.20	318.35	63.00	487.20	716.38
142.74	367.50	110.09	313.28	130.40	154.10	159.18	63.00	243.60	500.69

INNOVATIVE	TRADITIONAL	GENERAL	
391.74	3585.66	0	<b>3977.40</b>
HOG: 0	BG: 0		NA Deprec. 2184.57
			0.00%
			<b>TOTAL 2184.57</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 12/09/2017 <b>Hour :</b> 16:24 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	