

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 72031 KM |
| File nr. : | 1434506 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1HEJ603 / VF7SC8HR4EW541309 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/07/2014 |
| VFS-nr. : | | Color : | BLUE |
| Make + Model : | CITROEN / C3 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | ONBEKEND | Co2: | 99g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1398 |
| Gear box : | Manueel | Number of places: | |
| Number of gears: | 5 | Number of doors: | 5 |
| HP: | 68 | kW: | 50 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | | Oil level : | OK | [x] |
| | | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|----------|----------|-----------|-----------|
| Wheel FL: | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | | | |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | | | |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | / | Hubcap : | [x] | SCRATCHED |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | [x] | SCRATCHED | |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | / | Hubcap : | | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 185 | 65 | R | 15 | H |
| Rear tyre | 185 | 65 | R | 15 | H |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|--------------------------|---------------------------|---------------|-------|------------|
| [x] | REAR BUMPER /LEFT/CORNER | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 169.44 EUR | | 50 % | 169.44 EUR |

Interior

| | | | | | |
|-----|---|-------------------|---------------|-----------|-----------|
| [x] | SEAT REAR L | DIRTY | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | I 1 specifik-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | | 14.58 EUR | 14.58 EUR |

Others

| | | | | | |
|--------------------|----------------|-------------------|---------------|-------|-------|
| HUB CAP REAR RIGHT | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | | | 50 % | |
| HUB CAP FR | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | WHEEL CAP | 24.00 EUR | 50 % | 24.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 1 | 1 | WHEEL CAP | 24.00 EUR | 50 % | 24.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|-------|---|---|---|---|---|---|----|
| 48.00 | 169.44 | 14.58 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24.00 | 84.72 | 14.58 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 14.58 | 217.44 | 0 | 232.02 |
| HOG: 0 | BG: 1 | | NA Deprec. 123.30 |
| | | | 0.00% |
| | | | TOTAL 123.30 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 31/08/2017 Hour : 10:41 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |