

www.vabfleetservices.be Date: 08/09/2017 1/4

CHLJDQ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 156929 KM File nr. : Mileage start / arrival: 1434484 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EHC631 / WF0MXXGBWMCA67277 / E-File nr. : First registration: 30/11/2012 VFS-nr.: Color: **GREY** Make + Model : Fuel type : FORD / GALAXY **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: DELAWARE CONSULTING BVBA 139g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: **VEHICLE** Seats (minivan): 7 [x] Vehicle type: GALAXY Econetic Trend St&St DPF 115PK Country registration: **BELGIUM**

· · · · · · · · · · · · · · · · · · ·	- 10						
Variant car:	MONOVOLUME	Engine size:	1560				
Gear box :	Manueel	Number of places:	7				
Number of gears:	6	Number of doors:	5				
HP:	116	kW:	85				
Fisc HP		Imported vehicle:	No				
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							

Metallic paint:



08/09/2017 Date: www.vabfleetservices.be 2/4

Original registr. number: OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity:	OK	
Cert. of reg. copy / Part 2: OK	[x]	Insurance certificate :		
Warning vest: OK	[x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit: OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Summer tires

Fron	t tyre			215			(60		R		16	Н
		[x]		Width			Не	eight		Туре		Rim	Index
Wheel RES:	[x]			Tyre:		OK		/	Rim :		/	Hubcap :	
Wheel RR:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	

Front tyre 215 60 R 16 H	
Rear tyre 215 60 R 16 H	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 08/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT

CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER

DENT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

ſ	INNOVATIVE	TRADITIONAL	GENERAL		
Γ	63.00	0	0		63.00
Γ	HOG: 0	BG: 2		NA Deprec.	63.00
_				0.00%	

TOTAL 63.00



www.vabfleetservices.be Date: 08/09/2017 4/4

[x] = Status Modification

Pictures: No

rictares.										
CIRCUMS	TANCES		UNDER CONDITION - VEHICLE WET							
Extra Time :	0 min	Waiting time: 0 m	in	Towing time :	0 min					
		Reason:		Reason:						
NOT EXECUTED	: No			<u> </u>						
Reason:	. 110									
Remark:										
Prices in EUR	without VAT									
			To the MARKET CO							
Authorized by customer :			Executed by VAB Fleet S	ervices						
Remark authorized	l customer :									
Date :	08/09/2017	Hour: 09:10								
Company :										
	Fleet									
Executed by VAB I Services	ice									
E-Mail :	@									
Signature authorized	by customer									
-			_							
		_								