

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	105116 KM
File nr. :	1435906	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DTA625 / VF1JK1JC647666144 /		yr of constructionr :	/
E-File nr. :		First registration :	17/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND ESPACE	Fuel type :	DIESEL
Object nr. :	42809	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SIPEF NV	Co2:	170g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.ESPACE Initiale FAP 149PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1995
Gear box :	Manueel	Number of places:	
Number of gears:	6	Number of doors:	
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		DENT						
	Number	Code	Description	Unit price	Depr.	Total			
1	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR			
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE						
			Repair paint - LI	New paint - E	Depr.	Total			
3	0 LU =0.00 EUR		369.84 EUR		50 %	369.84 EUR			
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE						
			Repair paint - LI	New paint - E	Depr.	Total			
3	0 LU =0.00 EUR		382.02 EUR		50 %	382.02 EUR			
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE						
			Repair paint - LI	New paint - E	Depr.	Total			
2	0 LU =0.00 EUR		382.02 EUR		50 %	382.02 EUR			

1	2	3	4	5	6	7	8	9	10
110.64	382.02	751.86	0	0	0	0	0	0	0
110.64	191.01	375.93	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	1133.88	0	1244.52
HOG: 0	BG: 2		NA Deprec. 677.58
			0.00%
			TOTAL 677.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 12:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	