

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	193513 KM
File nr. :	1436338	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YZ6938 / W0LJ7A4ASDV607298 /		yr of constructionr :	/
E-File nr. :		First registration :	15/05/2013
VFS-nr. :		Color :	WHITE
Make + Model :	OPEL / VIVARO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	MOVILLIAT CONSTRUCTION SA	Co2:	g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	9 [x]
Vehicle type :	VIVARO 2700 COMBI L1H1 HD DPF(E5) 90PK	Country registration :	LUXEMBOURG

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1995
Gear box :	Manueel	Number of places:	9
Number of gears:	6	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD		
Mobile phone kit :		Car radio :	OK	[x]
First aid kit :	OK	[x]		
Jack, wheelspanner :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	
Rear tyre	205	65	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] WINDSCREEN/CENTER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
4	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR	
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE	+DEUK EN ROEST VORMING		
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	226.26 EUR		50 %	226.26 EUR	
[x]	THRESHOLD FRONT/LEFT/CENTER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
2	40 LU =192.00 EUR	0 EUR	310.50 EUR	50 %	502.50 EUR	
[x]	FRONT DOOR/LEFT/CENTER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
2	30 LU =144.00 EUR	0 EUR	326.78 EUR	50 %	470.78 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total	
3	I1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR	
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
	Number Code	Description	Unit price	Depr.	Total	
0	0					

Interior

[x] SEAT FL CUT / TORN

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-02	SUPPL VINYL REPAIR	18.00 EUR	18.00 EUR

[x] SEAT REAR RIGHT CUT / TORN

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-02	SUPPL VINYL REPAIR	18.00 EUR	18.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR
Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvnl-02	SUPPL VINYL REPAIR	18.00 EUR	18.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 8	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	91.76 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DOOR FL	377.10 EUR	50 %	377.10 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	DOORSTEP	187.50 EUR	50 %	187.50 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR

1	2	3	4	5	6	7	8	9	10
91.76	1537.88	110.64	329.40	300.60	226.26	0	0	0	0
91.76	768.94	110.64	164.70	300.60	113.13	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
503.00	2093.54	0	2596.54
HOG: 0	BG: 3		NA Deprec. 1549.77
			0.00%
			TOTAL 1549.77

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 14:04 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	