

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                                     |                                 |                               |
|-------------------------------------|-------------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING                     | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                                     | <b>Mileage :</b>                | 113422 KM                     |
| <b>File nr. :</b>                   | 1435623                             | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                                     | <b>Mileag ref. service :</b>    | 0                             |
| 1FJR781 / W0LPE9E3XD2103698 /       |                                     | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                                     | <b>First registration :</b>     | 18/07/2013                    |
| <b>VFS-nr. :</b>                    |                                     | <b>Color :</b>                  | BROWN                         |
| <b>Make + Model :</b>               | OPEL / ZAFIRA                       | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 61232                               | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                                     | <b>Environment Class:</b>       | EURO 6                        |
| <b>Customer company :</b>           | ELSTER NV/ESSEN                     | <b>Co2:</b>                     | 109g/km                       |
| <b>Driver :</b>                     |                                     | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | LEATHER                             | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               |                                     | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | ZAFIRA TOURER ecoFL.Cosmo S/S 135PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |            |                            |         |
|-------------------------------------|------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No         | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | MONOVOLUME | <b>Engine size:</b>        | 1598    |
| <b>Gear box :</b>                   | Manueel    | <b>Number of places:</b>   | 7       |
| <b>Number of gears:</b>             | 6          | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 136        | <b>kW:</b>                 | 100     |
| <b>Fisc HP</b>                      |            | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No         | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |            | <b>Extra set of tires:</b> | No      |
|                                     |            | <b>Use:</b>                | Unknown |

**General condition:**

|                              |    |                       |                         |     |
|------------------------------|----|-----------------------|-------------------------|-----|
| Original registr. number :   | OK | Service manual :      | OK                      | [x] |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |     |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |     |
| Warning vest :               |    | Transport licence :   |                         |     |
| Tax certificate :            |    | Navigation CD/SD/DVD  |                         |     |
| Fuel card :                  |    | Car radio :           | OK                      | [x] |
| Mobile phone kit :           |    | Extinguisher :        | OK                      | [x] |
| First aid kit :              | OK | [x]                   | Warning triangle :      | OK  |
| Jack, wheelspanner :         | OK | [x]                   | Oil level :             | OK  |
|                              |    |                       | Filled up :             | 0   |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |      |       |       |          |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|
| Wheel FL:  | [x] | KLÉBER   | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |
| Wheel FR : | [x] | KLÉBER   | Tyre : | [x] | OK  | [x]  | 4-6/  | Rim : | /        |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |
| Wheel RES: | [x] | KLÉBER   | Tyre : | OK  | [x] | >6/  | Rim : | /     | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 50     | R    | 17  | W     |
| Rear tyre  | 225   | 50     | R    | 17  | W     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] ROOF/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE) POLIJSTEN
- [x] REAR DOOR/RIGHT/FRONT DENT
- [x] ROOF/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE) POLIJSTEN

### Accessories and others

- [x] OUTSIDE MIRROR SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

- [x] FRONT THRESHOLD/LEFT/FRONT

DENT

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 310.50 EUR        |               | 50 %  | 310.50 EUR |

| 1      | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|---|---|---|---|---|---|---|---|----|
| 310.50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 155.25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 0          | 310.50      | 0       | <b>310.50</b>       |
| HOG: 0     | BG: 0       |         | NA Deprec. 155.25   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 155.25</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 08/09/2017 <b>Hour :</b> 09:21<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |