

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	97274 KM
File nr. :	1435900	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DRJ866 / VF38URHC8CL057838 /		yr of constructionr :	/
E-File nr. :		First registration :	01/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / 508	Fuel type :	DIESEL
Object nr. :	60008	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BEYERS NV	Co2:	107g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	508 SW RXH BMP STT 163PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1997
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]		/	Hubcap :	
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	Y
Rear tyre	245	45	R	18	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR DOOR/LEFT/REAR	DENT
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x]	DOOR IN FL	OTHER DAMAGES
[x]	BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
4	20 LU =96.00 EUR		211.80 EUR		50 %
					307.80 EUR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
8	20 LU =96.00 EUR		0 EUR		50 %
					96.00 EUR
[x]	REAR WINDOW STYLE/CENTER/RIGHT/UP	DENT			
	Number	Code	Description	Unit price	Depr.
					Total
6	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
5	0 LU =0.00 EUR		310.50 EUR		50 %
					310.50 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	15 LU =72.00 EUR		318.35 EUR		50 %
					390.35 EUR

[x]	BONNET/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CHROOM	120.00 EUR	50 %	120.00 EUR
4	1	CHROOM	120.00 EUR	50 %	120.00 EUR
8	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
331.80	290.08	390.35	427.80	310.50	63.00	285.00	346.00	0	0
165.90	145.04	195.18	213.90	155.25	63.00	285.00	173.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
348.00	2096.53	0	2444.53
HOG: 0	BG: 0		NA Deprec. 1396.26
			0.00%
			TOTAL 1396.26

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 10:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	