

www.vabfleetservices.be Date: 07/09/2017 1/4

CK2ZWE

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Covering:

Vehicle kind:

Vehicle type:

General condition:

TISSUE

VEHICLE

PASSAT VAR Comfortline 105PK

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 113750 KM File nr. : Mileage start / arrival: 0 / 01436453 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DUR357 / WVWZZZ3CZCE110904 / E-File nr. : First registration: 03/09/2012 VFS-nr.: Color: **GREY** Make + Model : Fuel type : VOLKSWAGEN / PASSAT BREAK **DIESEL** Object nr. : Fuel: 11327 Classification: **Environment Class:** EURO 5 Customer company: Co2: **KBC BANK NV** 116g/km Driver : Remote controls:

Number keys:

Seats (minivan):

Country registration:

1 [x]

BELGIUM

0

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown



www.vabfleetservices.be Date: 07/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

			/idth	4			eight			Type	Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:			Hubcap:	
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:			Hubcap:	
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:			Hubcap:	
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	
Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	

[x]	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: www.vabfleetservices.be 07/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows [x] REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE DENT [x] REAR DOOR/RIGHT/FRONT FRONT DOOR/LEFT/REAR DENT [x] SCRATCH WITH PAINT DAMAGE FRONT MUDGUARD/LEFT/CENTER [x] BONNET/CENTER/LEFT DENT [x]

Во	dywork \& windows					
x]	FRONT DOOR/RIGHT/REAR		DENT			
	Number Code	Description		Unit price	Depr.	Total
	2 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
	Number Code	Description		Unit price	Depr.	Total
	2 I 1 i-vab-uitd-02	BEAT OUT DENT SU	PPL	19.80 EUR		19.80 EUR
:]	FRONT/LEFT		HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E		Depr.	Total
	1 5 LU =24.00 EUR	0 EUR	1		50 %	24.00 EUR

1 10003					
Number	Code	Description	Unit price	Depr.	Total
1 1	FRONT		28.80 EUR	50 %	28.80 EUR

1	2	3	4	5	6	7	8	9	10
52.80	82.80	0	0	0	0	0	0	0	0
26.40	82.80	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
82.80	52.80	0		135.60
HOG: 0	BG: 0		NA Deprec.	109.20
			0.00%	

TOTAL

109.20



4/4

07/09/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Waiting time : Extra Time : $0 \min$ 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date : 07/09/2017 Hour: 11:07 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer