

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	112643 KM
File nr. :	1436220	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DSC672 / VF3XU9HM0CZ039538 /		yr of constructionr :	/
E-File nr. :		First registration :	08/08/2012
VFS-nr. :		Color :	WHITE
Make + Model :	PEUGEOT / EXPERT	Fuel type :	DIESEL
Object nr. :	72417	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC BUILDING SERVICES	Co2:	177g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	EXPERT B/F MWB 229 L2H1 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1560
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	M+S
Rear tyre	215	60	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] FRONT BUMPER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

Interior

- [x] SEAT FL OTHER DAMAGES

Accessories and others

- [x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I3	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		43.74 EUR

1	2	3	4	5	6	7	8	9	10
43.74	0	0	0	0	0	0	0	0	0
43.74	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.74	0	0	43.74
HOG: 0	BG: 3		NA Deprec. 43.74
			0.00%
			TOTAL 43.74

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 09:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	