

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	105562 KM
<b>File nr. :</b>	1435888	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EFB202 / VF30A9HR8CS238098 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	13/11/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	PEUGEOT / 5008	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SOA PEOPLE SA	<b>Co2:</b>	114g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	5 [x]
<b>Vehicle type :</b>	5008 e-HDi Allure STT FAP BMP 112PK Aut.	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1560
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	112	<b>kW:</b>	82
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 1.6-2/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 1.6-2/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 1.6-2/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 1.6-2/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] ANDERE Tyre : OK [x] 2-4/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	WINTER H
Rear tyre	215	55	R	16	WINTER H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/Front	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE
[x]	LIGHTS/RIGHT/Front	SCRATCH WITH PAINT DAMAGE

### Interior

[x]	STEERING WHEEL	OTHER DAMAGES
-----	----------------	---------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	+DEUK		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR LIGHT/LEFT/CORNER	WINDOW DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	FRONT MUDGUARD/RIGHT/Front	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

## Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		WINDOW DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	0 EUR		50 %	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	MIRROR GLASS	18.00 EUR	50 %	18.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	CHROOMAFDEKPLAAT	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
133.56	325.80	451.98	0	0	0	0	0	0	0
124.56	162.90	225.99	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	795.78	0	<b>911.34</b>
HOG: 0	BG: 0		NA Deprec. 513.45
			0.00%
			<b>TOTAL 513.45</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK + 2 HOOFDTEL. [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 06/09/2017 <b>Hour :</b> 13:21 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	