

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	163361 KM
File nr. :	1437072	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HHU289 / WVWZZZ3CZFE013299 /		yr of constructionr :	/
E-File nr. :		First registration :	28/07/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	940	Fuel :	
Classification :	C	Environment Class:	EURO 5
Customer company :	THERABEL PHARMA NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/LEFT/REAR	DENT		
[x]	FRONT DOOR/LEFT/CENTER	DENT	2X	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	BONNET/CENTER/LEFT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES			MOTORPLAAT	
		Repair paint - LI	New paint - E		Depr.	Total
1	5 LU	=24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	MOTORPLAAT	200.00 EUR	50 %	200.00 EUR

1	2	3	4	5	6	7	8	9	10
224.00	115.56	63.00	115.56	0	0	0	0	0	0
112.00	115.56	63.00	115.56	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
294.12	224.00	0	518.12
HOG: 0	BG: 0		NA Deprec. 406.12
			0.00%
			TOTAL 406.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 15:05 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	