

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	171146 KM
File nr. :	1436455	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPK653 / VF1JZ00BD47676151 /		yr of constructionr :	/
E-File nr. :		First registration :	13/07/2012
VFS-nr. :		Color :	BROWN
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	37802	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Dynamiq.7pl.FAP 130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/CENTER/RIGHT DENT
- [x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

Interior

- [x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			Description	Unit price	Depr.
					Total
4	I 1 i-vab-sp-01	SPOTREPAIR		115.56 EUR	
					115.56 EUR
[x]	WINDOW FRONT DOOR/RIGHT	WINDOW DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	10 LU =48.00 EUR		0 EUR		50 %
					48.00 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		220.18 EUR		50 %
					220.18 EUR

[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	ROOF/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	ZIJRUIT	75.00 EUR	50 %	75.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	MIRROR COVER	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
1212.68	481.50	211.80	777.09	0	0	0	0	0	0
606.34	240.75	105.90	446.32	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	2567.51	0	2683.07
HOG: 0	BG: 0		NA Deprec. 1399.32
			0.00%
			TOTAL 1399.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 09:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	