

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	41777 KM
File nr. :	1429826	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FKL166 / YV1MV8481E2087484 /		yr of constructionr :	/
E-File nr. :		First registration :	26/07/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INT. CARRIER SERVICES NV	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	MICHELIN	Tyre :	OK		>6/	Rim :			/	Hubcap :	
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK		>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:		Tyre :	OK		/	Rim :			/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT		
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		
[x]	ROOF STYLE/CENTER/RECHTS	DENT		
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	INSTAP	
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	BONNET/CENTER/LEFT/FRONT	OTHER DAMAGES	INW POL	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/RIGHT	HOLE/CRACK/TORN			+MISTLICHT	
			Repair paint - LI	New paint - E	Depr.	Total
	2	5 LU =24.00 EUR	211.80 EUR		50 %	235.80 EUR
	Number	Code	Description	Unit price	Depr.	Total
	2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Interior

[x]	SEAT FR	DIRTY				
	Number	Code	Description	Unit price	Depr.	Total
	1	I 1 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
	2	1	FOG LAMP	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	436.44	63.00	0	0	0	0	0	0	0
14.58	273.54	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
188.22	325.80	0	514.02
HOG: 0	BG: 0		NA Deprec. 351.12
			0.00%
			TOTAL 351.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/09/2017 Hour : 11:51 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	