

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	93181 KM
File nr. :	1434003	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DUR382 / WVVZZZ1KZDW075969 /		yr of constructionr :	/
E-File nr. :		First registration :	03/09/2012
VFS-nr. :		Color :	SILVER
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	99g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GOLF BER BlueMotion DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/LEFT	CHIPS
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR
[x]	REAR LIGHT/RIGHT	WINDOW DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR		0 EUR		50 %
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR		308.20 EUR		50 %
					308.20 EUR
[x]	REAR DOOR/RIGHT/FRONT	DENT			
			Number	Code	Description
					Unit price
					Depr.
					Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	FRONT BUMPER/RIGHT	OTHER DAMAGES			HERMONTAGE
			Repair paint - LI	New paint - E	Depr.
					Total
1	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
72.00	301.80	308.20	63.00	95.00	0	0	0	0	0
36.00	150.90	154.10	63.00	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	682.00	0	840.00
HOG: 0	BG: 0		NA Deprec. 499.00
			0.00%
			TOTAL 499.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/09/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	