

CJU73L

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 125601 KM |
| File nr. : | 1436259 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FNT346 / WVWZZZ3CZEE035184 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 02/09/2013 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | VOLKSWAGEN / PASSAT | Fuel type : | DIESEL |
| Object nr. : | 63793 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BIOCARTIS NV | Co2: | 116g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | PASSAT VAR Comfortline BMT 105PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1598 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 105 | kW: | 77 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

General condition:

| | |
|--------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: OK [x] | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|--|
| Wheel FL: [x] FIRESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RL : [x] FIRESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel FR : [x] FIRESTONE Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RR : [x] FIRESTONE Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RES: [x] Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215 | 55 | R | 16 | H |
| Rear tyre | 215 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT DENT

| | Repair paint - LI | New paint - E | Depr. | Total |
|-------------------|-------------------|---------------|-------|------------|
| 1 5 LU =24.00 EUR | 211.80 EUR | | 50 % | 235.80 EUR |

[x] REAR BUMPER/SIDE/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-------|
| 0 | 0 | | | | |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|---|---|---|---|---|---|---|---|----|
| 235.80 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 117.90 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 0 | 235.80 | 0 | 235.80 |
| HOG: 0 | BG: 0 | | NA Deprec. 117.90 |
| | | | 0.00% |
| | | | TOTAL 117.90 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 11:12 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |