

www.vabfleetservices.be Date: 14/09/2017 1/4

CLJ00G

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar:	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	60486 KM
File nr. :	1437592	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HUE908 / WBA3Y11050D	450503 /	yr of constructionr :	/
E-File nr. :		First registration :	03/10/2014
VFS-nr. :		Color :	WHITE
Make + Model :	BMW / 3 GT	Fuel type :	DIESEL
Object nr. :	34805	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	Devoteam NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	



www.vabfleetservices.be Date: 14/09/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

	[x] Width			Height			Туре		Rim	Index			
Wheel RES:	[x]		Tyre:		OK		/	Rim:				Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	

	[x]	Width	Height	Type	Rim	Index
Fr	ront tyre	225	55	R	17	V
R	Rear tyre	225	55	R	17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 14/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[X] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT/LEFT CHIPS

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 2		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 14/09/2017 4/4

[x] = Status Modification

Pictures: No

rictares. 100								
CIRCUMSTANCES			NORMAL CONC	NORMAL CONCLUSION				
Extra Time :	0 min		min	Towing time :	0 min			
		Reason:		Reason:				
NOT EXECUTED :	No							
Reason:	110							
Remark :	,							
Prices in EUR v	vithout VAT							
Authorized by			Executed by VAB Flee	Comings	1			
Authorized by customer :			Executed by VAB Fice	i Services				
Remark authorized	customer:							
Date :	14/09/2017	Hour: 12:15						
Company :								
Executed by VAB F Services	leet							
E-Mail :	@							
Signature authorized	by customer		- 					
-		<i></i>	+					
	_							
_								