

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 129054 KM |
| File nr. : | 1436345 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| JS9565 / WDD2462011J201899 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 11/09/2013 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | MERCEDES / B | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | |
| Customer company : | BEMO EUROPE - BANQUE PRIVEE | Co2: | g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | B 200 CDI BE 136PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | |
| Variant car: | | Engine size: | 1796 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | | Service manual : | |
| Cert. of reg. / Part 1: | | Cert. of conformity : | |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK [x] | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 45 | R | 17 | Y |
| Rear tyre | 225 | 45 | R | 17 | Y |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--|--------|----|---|-------|---|----------|
| Wheel FL: | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|--|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : DOCUMENTEN WORDEN NAGESTUURD [x] | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 15:45 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |