

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	135292 KM
File nr. :	1436806	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DNR395 / YV1MW84F1C2696545 /		yr of constructionr :	/
E-File nr. :		First registration :	02/07/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V50	Fuel type :	DIESEL
Object nr. :	48582	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SPIE BELGIUM NV/SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V50 BRE DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	[x]
Tax certificate :	[x]	Navigation CD/SD/DVD	OK
Fuel card :	[x]	Car radio :	OK
Mobile phone kit :	[x]	Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	M+S
Rear tyre	205	55	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/SIDE/LEFTCENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/LEFT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] ROOF/CENTER/RIGHT OTHER DAMAGES CHEMISCHE INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

[x] FRONT MUDGUARD/LEFT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN DOWN / DAMAGED

	Repair paint - LI	New paint - E	Depr.	Total
5 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	INDICATOR	15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	481.50	220.18	520.00	39.00	0	0	0	0	0
105.90	240.75	110.09	260.00	19.50	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1472.48	0	1472.48
HOG: 0	BG: 0		NA Deprec. 736.24
			0.00%
			TOTAL 736.24

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 16:06 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	