

www.vabfleetservices.be Date: 21/09/2017 1/4

CNW107

#### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 63721 KM File nr. : Mileage start / arrival: 0 / 01439415 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FNJ380 / WAUZZZ8V8EA046367 / E-File nr. : First registration: 28/08/2013 Color: VFS-nr.: **SILVER** Make + Model : Fuel type : AUDI / A3 **DIESEL** Object nr. : Fuel: 4457 Classification: **Environment Class:** EURO 5 Customer company: Co2: Clarins Belgique 106g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: **VEHICLE** Seats (minivan): 0 Vehicle type: A3 BER Attraction 150PK Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	3
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 21/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

## Wheels and tyres: Summer tires

		[x] W	idth			Н	eight			Туре		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHEE	)	/ Hubcap:	
Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHEL	)	/ Hubcap:	

[x	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark:

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 21/09/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

В	OC	lyw	ork	:\&	wir	1d(	ows
---	----	-----	-----	-----	-----	-----	-----

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/FRONT DENT

#### STATUS: NOT ACCEPTABLE

[x] THRESHOLD FRONT/LEFT/CENTER DENT

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 248.40 EUR
 50 %
 248.40 EUR

#### Others

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
248.40	190.00	0	0	0	0	0	0	0	0
124.20	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
190.00	248.40	0		438.40
HOG: 0	BG: 1		NA Deprec.	314.20
			0.00%	

0.00%
TOTAL 314.20



www.vabfleetservices.be Date: 21/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES		NORMAL CONCLUSION			
Extra Time :	0 min	Waiting time : Reason :	0 min	Towing time : Reason :	0 min
NOT EXECUTED : Reason :	: No				
Remark :					
Prices in EUR v	vithout VAT				
Authorized by customer :			Executed by VAB F	leet Services	
Remark authorized	customer :				
Date :	21/09/2017	<b>Hour:</b> 09:15			
Company:					
Executed by VAB F Services	leet				
E-Mail :	@				
Signature authorized	by customer				
<u> </u>					