

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|--------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 163760 KM |
| File nr. : | 1436749 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FNT581 / WBA3D11000J850806 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 02/09/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | BMW / 3 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | DELAWARE CONSULTING BVBA | Co2: | 114g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | IMITATION LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | 3 BER 318dA 136PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BERLINE | Engine size: | 1995 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 4 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|-----|-------------------------|--------|
| Original registr. number : | OK | Service manual : | [x] |
| Cert. of reg. / Part 1: | OK | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | [x] | Insurance certificate : | [x] |
| Warning vest : | OK | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | OK |
| Mobile phone kit : | | Extinguisher : | OK |
| First aid kit : | OK | Warning triangle : | OK |
| Jack, wheelspanner : | [x] | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | |
|------------|-----|----------|--------|----|------|-------|---|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | 4-6/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | OK | 2-4/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | 4-6/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 60 | R | 16 | H |
| Rear tyre | 205 | 60 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--|--------|----|---|-------|---|----------|
| Wheel FL: | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|--------------------------|---------------------------|
| [x] | REAR MUDGUARD/LEFT/REAR | DENT |
| [x] | REAR DOOR/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE |
| | BONNET/CENTER/LEFT/FRONT | CHIPS |
| [x] | FRONT BUMPER/LEFT | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT BUMPER/RIGHT | CHIPS |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|---|---|---|---|---|---|---|---|---|----|
| 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 0 | 0 | 0 | 0 |
| HOG: 0 | BG: 0 | | NA Deprec. 0 |
| | | | 0.00% |
| | | | TOTAL 0 |


[x] = Status Modification

Pictures : No

CIRCUMSTANCES

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : ONDERHOUDSBOEKJE = ENKEL ELECTRONISCH | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 13:53 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |