

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	146545 KM
File nr. :	1438356	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CXM548 / WAUZZZ4G1CN133685 /		yr of constructionr :	/
E-File nr. :		First registration :	20/03/2012
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A6 AVANT	Fuel type :	DIESEL
Object nr. :	69117	Fuel :	
Classification :	L	Environment Class:	EURO 5
Customer company :	VSK ELECTRONICS NV	Co2:	135g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A6 AVANT Multitr.163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] BRIDGESTONE Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	16	Y
Rear tyre	225	60	R	16	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

- [x] BONNET/CENTER/LEFT/FRONT CHIPS
- [x] BONNET/CENTER/RIGHT/FRONT CHIPS
- [x] FRONT BUMPER/LEFT CHIPS
- [x] FRONT BUMPER/RIGHT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 10 LU =48.00 EUR	369.84 EUR		50 %	417.84 EUR

1	2	3	4	5	6	7	8	9	10
417.84	0	0	0	0	0	0	0	0	0
208.92	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	417.84	0	417.84
HOG: 0	BG: 2		NA Deprec. 208.92
			0.00%
			TOTAL 208.92

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 11:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer <hr/>	