

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	105171 KM
File nr. :	1437424	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPK810 / WAUZZZ8K2DA197029 /		yr of constructionr :	/
E-File nr. :		First registration :	14/02/2013
VFS-nr. :		Color :	BLUE
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	12217	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	I.B.A. SA	Co2:	117g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A4 BER TDi 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	Y
Rear tyre	225	55	R	16	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/REAR DENT
- [x] ROOF/REAR/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/LEFT/REAR		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
4	10 LU =48.00 EUR	308.20 EUR		50 %	356.20 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		DENT		
	Number Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	220.18 EUR		50 %	268.18 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	BONNET/CENTER/RIGHT/FRONT		CHIPS	ROEST	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	211.80 EUR		50 %	259.80 EUR

Interior

[x] SEAT REAR L STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	643.54	290.08	678.64	63.00	95.00	0	0	0	0
14.58	379.55	145.04	394.64	63.00	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
398.78	1386.06	0	1784.84
HOG: 0	BG: 0		NA Deprec. 1091.81
			0.00%
			TOTAL 1091.81

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 09:37 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer <hr/>	