

CL6GI1

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	131218 KM
File nr. :	1437310	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CUQ339 / WAUZZZ4G0CN099660 /		yr of constructionr :	/
E-File nr. :		First registration :	01/03/2012
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A6 AVANT	Fuel type :	DIESEL
Object nr. :	52323	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LUFTHANSA TECHNIK BRUSSELS NV	Co2:	135g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A6 AVANT Multitr.163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	[x]
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	16	Y
Rear tyre	225	60	R	16	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES	SLECHTE HERSTELLING
-----	-------------------	---------------	---------------------

Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		72.90 EUR

1	2	3	4	5	6	7	8	9	10
72.90	0	0	0	0	0	0	0	0	0
72.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
72.90	0	0	72.90
HOG: 0	BG: 2		NA Deprec. 72.90
			0.00%
			TOTAL 72.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/09/2017 Hour : 08:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	