

www.vabfleetservices.be Date: 20/09/2017 1/4

CNLG6X

[X] EFFECTIVE [] NOT EXECUTED []] COLLECTION	[] DELIVERY
------------------------------------	--------------	--------------

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: CLEAN [x]

Owner: Mileage: 117974 KM

File nr.: 1439191 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref : Mileag ref. service : 0

QL4528 / WAUZZZ8R9EA082488 / yr of constructionr : /

E-File nr.: First registration: 14/02/2014

VFS-nr.: Color: BLACK

Make + Model: AUDI / Q3 Fuel type: DIESEL

Object nr.: ONBEKEND Fuel:

Classification : Environment Class:

Customer company: ONBEKEND Co2: g/km

Driver: Remote controls: 2

Covering: LEATHER Number keys: 2[x] Vehicle kind: VEHICLE Seats (minivan): 0

Vehicle type : Country registration : BELGIUM

blbGiciv

VAT over the margin - car: Metallic paint:

Variant car: SUV Engine size: 1968

Gear box: Automaat algemeen Number of places: 5

Number of gears: Number of doors: 5

HP: 177 kW: 130

Fisc HP Imported vehicle: No

Animals transported: No Smoked in vehicle: No

Use: Unknown

Extra set of tires:

No

General condition:

Due date vehicle inspection:



www.vabfleetservices.be Date: 20/09/2017 2/4

Original registr. number :	Service manual: OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest: OK [x]	Transport licence :
Tax certificate:	Navigation CD/SD/DVD
Fuel card :	Car radio: OK [x]
Mobile phone kit :	Extinguisher: OK [x]
	Warning triangle: OK [x]
First aid kit: OK [x]	Oil level: OK [x]
Jack, wheelspanner: OK [x]	Filled up: 0

Wheels and tyres: Summer tires

	r tyro		235				55		P		17	W
Fron	t tyre		235			6	55		R		17	W
		[x]	Width			He	ight		Туре		Rim	Index
Wheel RES:	[x]	ANDERE	Tyre:		OK	[x]	>6 /	Rim :		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	>6/	Rim:		/	Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap:	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 20/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER DENT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
63.00	0	0	63.00
NA Deprec. 63.00		BG: 0	HOG: 0
0.00%			

TOTAL

63.00



www.vabfleetservices.be Date: 20/09/2017 4/4

[x] = Status Modification

Pictures: No

NORMAL CONCLUSION					ANCES	CIRCUMSTA
0 min	Towing time : Reason :			Waiting t Reason :	0 min	Extra Time :
					No	NOT EXECUTED : Reason :
						Remark :
					chout VAT	Prices in EUR with
	rvices	Executed by VAB Fleet Se				Authorized by customer :
					stomer :	Remark authorized cus
			13:10	Hour :	20/09/2017	Date :
					t	Company : Executed by VAB Fleet Services
					@	E-Mail :
			_		customer	Signature authorized by