

www.vabfleetservices.be Date: 14/09/2017 1/4

CMK31L

[X] EFFECTIVE	[] NOT EXECUTED	[] COLLECTION	[] DELIVERY
[A] EFFECTIVE	[] NOT EXECUTED	[]COLLECTION	[]DELIVERI

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage:	122198 KM
File nr. :	1438417	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWC526 / WF0JXXWPBJC	D17697 /	yr of constructionr :	/
E-File nr. :		First registration :	14/09/2012
VFS-nr. :		Color :	BLUE D
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0 [x]
Vehicle type :	C-MAX Titanium St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 14/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :		
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel FR:	[x]	MICHELIN	Tyre: $[x]$] OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	/ Hubcap:
Wheel RES:	[x]	MICHELIN	Tyre:	OK		/	Rim:	/ Hubcap:

[x] Width		Height	Туре	Rim	Index	
Front tyre	215	55	R	16	Н	
Rear tyre	215	55	R	16	Н	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 14/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	REAR DOOR/LEFT/CENTER	CHIPS
[x]	ROOF/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT	DENT
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

п	n	•	$\boldsymbol{\wedge}$	io	r	
		ш.	┖	 u		

[x] LUGGAGE COVER MISSING/INCOMPLETE

Repair paint - LI New paint - E Depr. Total

1 0 LU =0.00 EUR 0 EUR 50 %

Pieces	2
--------	---

	1 1000							
•	Number	Code	Description	Unit price	Depr.	Total		
	1 1	BACK SHELF		50.00 EUR	50 %	50.00 EUR		

1	2	3	4	5	6	7	8	9	10
50.00	0	0	0	0	0	0	0	0	0
25.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
50.00	0	50.00	0
NA Deprec. 25.00		BG: 0	HOG: 0
0.00%			

TOTAL 25.00



www.vabfleetservices.be Date: 14/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS'	TANCES		UNDER CONDITION - VEHICLE WET						
Extra Time :	0 min	Waiting time: 0 m Reason:	nin	Towing time: 0 min Reason:					
NOT EXECUTED : Reason :	No	!							
Remark :									
Prices in EUR w	vithout VAT								
Authorized by customer:			Executed by VAI	B Fleet Services					
Remark authorized HOEDENPLANK W	customer : ORDT NOG BINNENGE	EBRACHT							
Date :	14/09/2017	Hour: 14:48							
Company:									
Executed by VAB Fl Services	leet								
E-Mail :	@								
Signature authorized	by customer								