

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	150410 KM
<b>File nr. :</b>	1438552	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
JM5559 / SALVA2DC5CH646829 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	09/03/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	LAND ROVER / EVOQUE	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	Acson SA Succursale de Luxembourg	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	PARTIAL LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	EVOQUE TD4 4WD Pure 150PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	2179
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	4
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	150	<b>kW:</b>	110
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	Service manual :	OK	[x]
Cert. of reg. / Part 1:	Cert. of conformity :		
Cert. of reg. copy / Part 2:	Insurance certificate :		
Warning vest :	Transport licence :		
Tax certificate :	Navigation CD/SD/DVD		
Fuel card :	Car radio :	OK	[x]
Mobile phone kit :	Extinguisher :		
First aid kit :	Warning triangle :	OK	[x]
Jack, wheelspanner :	Oil level :	OK	[x]
	OK	[x]	
	Filled up :	0	

## Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	60	R	18	M+S
Rear tyre	235	60	R	18	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x] FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		REPARATION CLIENT !!!!	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR
[x] FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	264.21	110.64	0	0	0	0	0	0	0
115.56	132.10	110.64	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
226.20	264.21	0	<b>490.41</b>
HOG: 0	BG: 2		NA Deprec. 358.30
			0.00%
			<b>TOTAL 358.30</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 19/09/2017 <b>Hour :</b> 11:32 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	