

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	185121 KM
File nr. :	1439194	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :	ZC6248 / WBAWZ510X00M01807 /	Mileag ref. service :	0
E-File nr. :		yr of constructionr :	/
VFS-nr. :		First registration :	03/10/2014
Make + Model :	BMW / X3	Color :	GREY
Object nr. :	ONBEKEND	Fuel type :	DIESEL
Classification :		Fuel :	
Customer company :	ONBEKEND	Environment Class:	
Driver :		Co2:	g/km
Covering :	TISSUE	Remote controls:	2
Vehicle kind :	VEHICLE	Number keys :	2 [x]
Vehicle type :		Seats (minivan) :	0
		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD		
Mobile phone kit :		Car radio :	OK	[x]
First aid kit :	OK	[x]		
Jack, wheelspanner :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	PIRELLI	Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	BINNENIN ISOLATIE
		Repair paint - LI	New paint - E
1	0 LU =0.00 EUR	0 EUR	50 %
		Repair paint - LI	New paint - E
1	5 LU =24.00 EUR	0 EUR	50 %
			24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
74.00	0	0	0	0	0	0	0	0	0
37.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	74.00	0	74.00
HOG: 0	BG: 0		NA Deprec. 37.00
			0.00%
			TOTAL 37.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/09/2017 Hour : 11:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	