

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	199765 KM
File nr. :	1437856	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GJU116 / WF0GXXGBBGEY25384 /		yr of constructionr :	/
E-File nr. :		First registration :	26/02/2014
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / MONDEO CLIPPER	Fuel type :	DIESEL
Object nr. :	8952	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BAM CONTRACTORS	Co2:	120g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1997
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	W
Rear tyre	215	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES	HAGELSCHADE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	REAR THRESHOLD/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	40 LU =192.00 EUR	0 EUR	414.00 EUR	50 %	606.00 EUR
[x]	WINDSCREEN/CENTER/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
0	0				
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
0	0				

[x] FRONT BUMPER/RIGHT/CORNER

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
4	1	DOORSTEP	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	211.80	487.20	1712.88	0	0	0	0	0	0
95.00	105.90	243.60	856.44	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	2411.88	0	2506.88
HOG: 0	BG: 0		NA Deprec. 1300.94
			0.00%
			TOTAL 1300.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/09/2017 Hour : 11:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	