

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 160464 KM |
| File nr. : | 1428472 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| JF3006 / VF7RWRHR8DL508289 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 26/04/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | CITROEN / C5 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | |
| Customer company : | ANIDRIS SA | Co2: | g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | C5 TOURER Exclusive Plus FAP 136PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1997 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | | Service manual : | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | Car radio : | OK [x] |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK [x] | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | | |
|------------|-----|----------|--------|------------|------|-------|---|----------|-----|--------------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : | [x] | MISSING/INCOMPLETE |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : | [x] | MISSING/INCOMPLETE |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] OK [x] | 2-4/ | Rim : | / | Hubcap : | [x] | MISSING/INCOMPLETE |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK [x] | 2-4/ | Rim : | / | Hubcap : | [x] | MISSING/INCOMPLETE |
| Wheel RES: | [x] | | Tyre : | OK | / | Rim : | / | Hubcap : | | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 60 | R | 16 | M+S |
| Rear tyre | 225 | 60 | R | 16 | M+S |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : | |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|--------------------------|--------------------------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT DOOR/RIGHT/REAR | DENT |
| [x] | FRONT BUMPER/RIGHT | SCRATCH WITH PAINT DAMAGE |

Accessories and others

| | | |
|-----|-------------------------------|---------------------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE | SCRATCH WITH PAINT DAMAGE |
|-----|-------------------------------|---------------------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | |
|-----|------------------------|---------------|
| [x] | FRONT BUMPER/LEFT/SIDE | OTHER DAMAGES |
|-----|------------------------|---------------|

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|----------------|------------------|-----------|-----------|
| 1 | I 1 | i-vab-ander-01 | REPAIR (PER 15') | 18.74 EUR | 18.74 EUR |

Others

| | | | | | |
|--------------------|----------------|-------------------|---------------|-------|-------|
| HUB CAP FL | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | | 50 % | |
| HUB CAP REAR L | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | | 50 % | |
| HUB CAP REAR RIGHT | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | | 50 % | |
| HUB CAP FR | | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 2 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|---|---|---|---|---|---|---|----|
| 18.74 | 120.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18.74 | 60.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|--------------------|
| 18.74 | 120.00 | 0 | 138.74 |
| HOG: 0 | BG: 0 | | NA Deprec. 78.74 |
| | | | 0.00% |
| | | | TOTAL 78.74 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

| | | |
|--|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : DOCUMENTEN WORDEN NAGESTUURD [x] | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 18/08/2017 Hour : 13:45 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |