

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

|                                     |                              |                                 |                               |
|-------------------------------------|------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING              | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                              | <b>Mileage :</b>                | 114301 KM                     |
| <b>File nr. :</b>                   | 1439187                      | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                              | <b>Mileag ref. service :</b>    | 0                             |
| DU9212 / 2C4RLAB55CR272910 /        |                              | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                              | <b>First registration :</b>     | 04/06/2013                    |
| <b>VFS-nr. :</b>                    |                              | <b>Color :</b>                  | GREY                          |
| <b>Make + Model :</b>               | LANCIA / VOYAGER             | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 |                              | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                              | <b>Environment Class:</b>       |                               |
| <b>Customer company :</b>           | FERRERO INTERNATIONAL SA     | <b>Co2:</b>                     | g/km                          |
| <b>Driver :</b>                     |                              | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | LEATHER                      | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                      | <b>Seats (minivan) :</b>        | 7 [x]                         |
| <b>Vehicle type :</b>               | VOYAGER Gold Line 163PK Aut. | <b>Country registration :</b>   | LUXEMBOURG                    |

|                                     |                   |                            |         |
|-------------------------------------|-------------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No                | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | MONOVOLUME        | <b>Engine size:</b>        | 2776    |
| <b>Gear box :</b>                   | Automaat algemeen | <b>Number of places:</b>   | 7       |
| <b>Number of gears:</b>             |                   | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 163               | <b>kW:</b>                 | 120     |
| <b>Fisc HP</b>                      |                   | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No                | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |                   | <b>Extra set of tires:</b> | No      |
|                                     |                   | <b>Use:</b>                | Unknown |

**General condition:**

|                              |    |                         |    |     |
|------------------------------|----|-------------------------|----|-----|
| Original registr. number :   |    | Service manual :        | OK | [x] |
| Cert. of reg. / Part 1:      |    | Cert. of conformity :   |    |     |
| Cert. of reg. copy / Part 2: |    | Insurance certificate : |    | [x] |
| Warning vest :               | OK | Transport licence :     |    |     |
| Tax certificate :            |    | Navigation CD/SD/DVD    | OK | [x] |
| Fuel card :                  |    | Car radio :             | OK | [x] |
| Mobile phone kit :           |    | Extinguisher :          | OK | [x] |
| First aid kit :              | OK | Warning triangle :      | OK | [x] |
| Jack, wheelspanner :         |    | Oil level :             | OK | [x] |
|                              |    | Filled up :             | 0  |     |

## Wheels and tyres: Summer tires

|            |     |         |        |     |     |      |       |       |                 |                 |          |          |
|------------|-----|---------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL:  | [x] | PIRELLI | Tyre : | OK  | [x] | 2-4/ | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RL : | [x] | PIRELLI | Tyre : | OK  | [x] | >6/  | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel FR : | [x] | PIRELLI | Tyre : | [x] | OK  | [x]  | 2-4/  | Rim : | [x]             | WHEEL SCRATCHED | /        | Hubcap : |
| Wheel RR : | [x] | PIRELLI | Tyre : | OK  | [x] | >6/  | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RES: | [x] |         | Tyre : | OK  |     | /    | Rim : |       |                 | /               | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 65     | R    | 17  | H     |
| Rear tyre  | 225   | 65     | R    | 17  | H     |

Remark :

## Wheels and tyres:

|            |  |  |        |    |   |  |       |  |  |   |          |
|------------|--|--|--------|----|---|--|-------|--|--|---|----------|
| Wheel FL:  |  |  | Tyre : | OK | / |  | Rim : |  |  | / | Hubcap : |
| Wheel RL : |  |  | Tyre : | OK | / |  | Rim : |  |  | / | Hubcap : |
| Wheel FR : |  |  | Tyre : | OK | / |  | Rim : |  |  | / | Hubcap : |
| Wheel RR : |  |  | Tyre : | OK | / |  | Rim : |  |  | / | Hubcap : |
| Wheel RES: |  |  | Tyre : | OK | / |  | Rim : |  |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

| [x] |                       |                   |                           |       |                   |
|-----|-----------------------|-------------------|---------------------------|-------|-------------------|
|     | REAR DOOR/LEFT/CENTER |                   | SCRATCH WITH PAINT DAMAGE |       |                   |
|     |                       | Repair paint - LI | New paint - E             | Depr. | Total             |
| 1   | 0 LU =0.00 EUR        | 382.02 EUR        |                           | 50 %  | 382.02 EUR        |
| [x] | BONNET/CENTER/RIGHT   |                   | OTHER DAMAGES             |       | BINNENIN ISOLATIE |
|     |                       | Repair paint - LI | New paint - E             | Depr. | Total             |
| 2   | 0 LU =0.00 EUR        | 0 EUR             |                           | 50 %  |                   |
|     |                       | Repair paint - LI | New paint - E             | Depr. | Total             |
| 2   | 5 LU =24.00 EUR       | 0 EUR             |                           | 50 %  | 24.00 EUR         |

### Pieces

| Number | Code | Description | Unit price | Depr. | Total     |
|--------|------|-------------|------------|-------|-----------|
| 2      | 1    | ISOLATIE    | 50.00 EUR  | 50 %  | 50.00 EUR |

| 1      | 2     | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|---|---|---|---|---|---|---|----|
| 382.02 | 74.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 191.01 | 37.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 0          | 456.02      | 0       | <b>456.02</b>       |
| HOG: 0     | BG: 2       |         | NA Deprec. 228.01   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 228.01</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 20/09/2017 <b>Hour :</b> 13:18<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |