

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	107621 KM
<b>File nr. :</b>	1435179	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
YYB584 / WF0NXXTTFN8Y34625 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	10/02/2009
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	FORD / TRANSIT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	46260	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	CMI MAINTENANCE & INGENIERIE SA	<b>Co2:</b>	274g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	TRANSIT CH2C 460L EF LWB 140PK Ged.3.5T	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	No
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2402
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	4
<b>HP:</b>	140	<b>kW:</b>	103
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	R
Rear tyre	195	75	R	16	R

Remark : WIELKAST RA BESCHADIGD

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	OTHER DAMAGES
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
2	0 LU =0.00 EUR		231.15 EUR		50 %
					231.15 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	0 LU =0.00 EUR		231.15 EUR		50 %
					231.15 EUR
[x]	ROOF/FRONT/CENTER/RIGHT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
5	20 LU =96.00 EUR		361.13 EUR		50 %
					457.13 EUR
[x]	ROOF STYLE/FRONT/LEFT/FRONT	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	ROOF STYLE/FRONT/LEFT/CENTER	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	I 1 i-vab-kunst-01	PLASTICS REPAIR		110.64 EUR	
					110.64 EUR
[x]	ROOF STYLE/FRONT/RIGHT/FRONT	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
1	1	HOEKELEMENT	35.00 EUR	50 %	35.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	HOEKELEMENT	35.00 EUR	50 %	35.00 EUR

1	2	3	4	5	6	7	8	9	10
118.00	231.15	231.15	110.64	457.13	0	0	0	0	0
59.00	115.58	115.58	110.64	228.56	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	1037.43	0	<b>1148.07</b>
HOG: 0	BG: 3		NA Deprec. 629.36
			0.00%
			<b>TOTAL 629.36</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/09/2017 <b>Hour :</b> 14:07 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	