

APPRAISAL

www.vabfleetservices.be Date: 18/09/2017 1/4

CMO1F5

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	28883 KM
File nr. :	1438489	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KXL556 / WDD1760121V08	2376 /	yr of constructionr :	/
E-File nr. :		First registration :	24/07/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	3735	Fuel :	
Classification:	N	Environment Class:	EURO 6
Customer company :	KPMG BEDRIJFSREVISOREN	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

		_	
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



APPRAISAL

www.vabfleetservices.be Date: 18/09/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED Wheel RL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED Wheel RR: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: Wheel RES: [x] Tyre: OK / Rim: / Hubcap: [x] Width Height Type Rim Index	E			105			<u> </u>		n		1.5	TT
Wheel RL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED Wheel RR: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED Wheel RR: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap:			[x]	Width		Н	eight		Туре		Rim	Index
Wheel RL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: / Hubcap: [x] SCRATCHED	Wheel RES:	[x]		Tyre:	OK		/	Rim:		/	Hubcap:	
Wheel RL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap:	Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap:	
	Wheel FR:	[x]	MICHELIN	Tyre: [x	OK	[x]	2-4 /	Rim:		/	Hubcap: [x] SCRATCHED
Wheel FL: [x] MICHELIN Tyre: OK [x] 2-4/ Rim: / Hubcap: [x] SCRATCHED	Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap:	
	Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap: [x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	Н
Rear tyre	195	65	R	15	Н

Remark: 4 SEASONS BANDEN

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



HOG: 0

BG: 0

APPRAISAL

Date: 18/09/2017 www.vabfleetservices.be 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

odywork	\& window	S							
REAR B	UMPER/CENTER/	RIGHT			SCRATCH WITH	PAINT DAMAG	E		
TATUS	: NOT AC	CEPTAE	BLE						
odywork	\& window	S							
FRONT	BUMPER/CENTER	R/RIGHT			DENT				
			Repair pai	nt - LI	New paint - E		Depr.		Total
1 0 LU =0.	00 EUR		211.80 EUF	₹			50 %		211.80 EU
hers									
HUB CA	.P FL								
			Repair pai	nt - LI	New paint - E		Depr.		Total
2 0 LU =0.	00 EUR						50 %		
HUB CA	.P FR								
			Repair pai	nt - LI	New paint - E		Depr.		Total
2 0 LU =0.	00 EUR						50 %		
eces									
Number	Code		Description	1		Unit pri	ice Depr.		Total
2 1	WHEEL CAP					30.00 E	UR 50 %		30.00 EU
Number	Code		Description	1		Unit pri	ice Depr.		Total
2 1	WHEEL CAP					30.00 E	UR 50 %		30.00 EU
1	2	3	4	5	6	7	8	9	10
211.80	60.00	0	0	0	0	0	0	0	0
105.90	30.00	0	0	0	0	0	0	0	0
INNOVATIVE TRADIT		ITIONAL	TIONAL GENERAL						
	0	2	71.80		0				27

NA Deprec. 0.00% TOTAL

135.90

135.90



APPRAISAL

18/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

CIRCUMSTANCES		UNDER CONDITION - DUSTY VEHICLE				
Extra Time: 0 min	Waiting time: 0 min Reason:		owing time : eason :	0 min		
NOT EXECUTED: No Reason:						
Remark:						
Prices in EUR without VAT						
Authorized by customer:		Executed by VAB Fleet Service	ces			
Remark authorized customer :						
Date : 18/09/2017	Hour: 14:20					
Company:						
Executed by VAB Fleet Services						
E-Mail: @						
Signature authorized by customer						