

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	198496 KM
<b>File nr. :</b>	1436115	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FWY757 / WDD2042001G251427 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	22/11/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	MERCEDES / C BREAK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BAM MAT NV	<b>Co2:</b>	127g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	C BRE 180 CDI BlueEFF. S&S 120PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	2143
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	120	<b>kW:</b>	88
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :			/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/FRONT	DENT
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR THRESHOLD/RIGHT/REAR	WINDOW DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/LEFT	CHIPS
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/RIGHT	CHIPS

### Interior

[x]	SEAT FL	OTHER DAMAGES
-----	---------	---------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

**Interior**

[x] FLOOR BOOT STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

**Others**

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	220.18	520.00	380.00	0	0	0	0	0	0
14.58	110.09	260.00	380.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
394.58	740.18	0	1134.76
HOG: 0	BG: 0		NA Deprec. 764.67
			0.00%
			TOTAL 764.67

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b> CP GEBELD OM 12u35 WAS NOG ONDERWEG/ HAD VASTGEZETEN IN BRUSSEL/GEEN HANDTEKENING  <b>Date :</b> 14/09/2017 <b>Hour :</b> 12:34  <b>Company :</b>  <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	