

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 79179 KM |
| File nr. : | 1439830 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DUR342 / WDD2042011F994514 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 03/09/2012 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | MERCEDES / C BREAK | Fuel type : | DIESEL |
| Object nr. : | 64906 | Fuel : | |
| Classification : | K | Environment Class: | EURO 5 |
| Customer company : | K.U. LEUVEN - UZ LEUVEN | Co2: | 133g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | C BRE 200 CDI BlueEFF. S&S 136PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 2143 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|--------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 1.6-2/ | Rim : | | | / | Hubcap : | |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 1.6-2/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | [x] | >6/ | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 45 | R | 17 | W |
| Rear tyre | 225 | 45 | R | 17 | W |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|-------------------------|--------------------------------|----------|--|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) | | |
| [x] | WINDSCREEN/CENTER/RIGHT | WINDOW DAMAGE | HERSTELD | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|----------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR WINDOW/RIGHT | WINDOW DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 25 LU =120.00 EUR | 0 EUR | | 50 % | 120.00 EUR |
| [x] | REAR MUDGUARD/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 308.20 EUR | | 50 % | 308.20 EUR |
| [x] | REAR DOOR/LEFT/CENTER | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 4 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 4 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 4 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|------------|
| 2 | 1 | BACK WINDOW | 250.00 EUR | 50 % | 250.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---|---|---|---|---|----|
| 318.35 | 370.00 | 308.20 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 159.18 | 185.00 | 154.10 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 285.00 | 996.55 | 0 | 1281.55 |
| HOG: 0 | BG: 0 | | NA Deprec. 783.28 |
| | | | 0.00% |
| | | | TOTAL 783.28 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 20/09/2017 Hour : 10:45 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |